

Header


Title	Emergency Response Procedures Overview		
Submission ID	194727	Submitted By	Das, Pragati
Lineup Date	2025-01-08	Supervisor	Lachapelle, Rob-Admin
Site	Creighton Mine	Department/Job	TG222074
Shift	Nights	Crew	construction
Client Representative	Ironstone Minerals Co.	Contact Info	Ironstone Minerals Co., 555-0199, contact@ironstoneminerals.com
Safety Topic	Essential Steps for Effective Emergency Response in Mining Operations.		
Communication Notes	<ul style="list-style-type: none">- Identify emergency exits and assembly points.- Keep first aid kits accessible and stocked.- Conduct regular drills for all staff.- Appoint floor wardens for coordination.- Report incidents immediately to supervisors.- Review procedures quarterly for effectiveness.		
Workplace Impacts	Effective emergency response procedures minimize risks and enhance safety during incidents.		

A/B Transfer, Ramp

Silver Creek Mine

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Jumley, Kody	No	Full-Face Respirator or Airstream, Application of Barrier Cream, Self Rescuer	R6826 - Scissor Truck	North section, 250 meters from the main entrance, adjacent to the ore processing area.

Images



Lineup Details

Details
<div><div>- Excavator</div><div>- Hauler</div><div>- Drill Rig</div><div>- Grader</div><div>- Water Truck</div><div>- Bulldozer</div><div>- Rock Crusher</div></div>

Hazards

Location	Description
A/B Transfer, Ramp - Emerald Crest Mine	Observed ground instability led to a rock fall, risking worker safety and site integrity.
A/B Transfer, Ramp - Testing PD-2815	Testing PD-2815
A/B Transfer, Ramp - Silver Creek Mine	Ground instability observed; rockfalls occurred near the eastern slope, posing significant risks.
A/B Transfer, Ramp - Silver Creek Mine	Ground instability observed; rockfalls occurred near the eastern slope, posing significant risks.
A/B Transfer, Ramp - Silver Creek Mine	Implemented water sprays and dust suppressants to minimize airborne particulate exposure.
A/B Transfer, Ramp - Silver Oak Mining Operations.	Ground instability led to rockfall, risking personnel and equipment safety at mining site.
A/B Transfer, Ramp - Silver Creek Mining Operations	Ground shifted unexpectedly, leading to partial collapse near excavation site. Immediate evacuation.

Testing

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Arcand, Stephane	No		-	-

Images

Lineup Details

Details
Another workplace.

External Distribution

Distribution

Reviewers

Name	Position	Date
No Data Available		