Lineup

Header

Title	Daily Safety Protocols and Hazard Awareness		
Submission ID	194314	Submitted By	Duggal, Manmeet Singh
Lineup Date	2024-08-26	Supervisor	Lachapelle, Rob-Admin
Site	Creighton Mine	Department/Job	TG222074
Shift	Nights	Crew	Production
Client Representative	Ironwood Minerals Corporation	Contact Info	Ironwood Minerals Corporation, 123-456-7890, contact@ironwoodminerals.com
Safety Topic	Daily hazard inspections: Identifying risks to ensure a safe mining environment.		
Communication Notes	 Conduct daily safety briefings. Inspect equipment before use. Identify and report hazards immediately. Use proper PPE at all times. Maintain clear pathways and signage. Report near-misses for review. 		
Workplace Impacts	Daily safety protocols enhance awareness, reducing hazards and fostering a secure mining environment.		

6680L, 6800L, 7530L, 8400L, A-Belt

Diamond Creek Mine

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Duggal, Manmeet Singh	No	Fall Protection Systems, Leather or High Cuff Gloves (Fire Resistant)	225 - Epiroc Haulage Truck	Main pit junction, 50 meters east of the access road, near the excavation point.

Images

Lineup Details

Details

- Front-end Loader
- Excavator
- Haul Truck
- Dump Truck
- Drilling Rig
- Grader
- Water Truck

Hazards

Location	Description
6680L, 6800L, 7530L, 8400L, A-Belt - Regulatory Compliance Office	Falling rocks: Hazard of loose rocks falling from high walls or cliffs in a mine site.
6680L, 6800L, 7530L, 8400L, A-Belt - Tes	Test
6680L, 6800L, 7530L, 8400L, A-Belt - Evergreen Mineral Extraction Site	Ground instability caused rock falls, endangering personnel and equipment. Immediate evacuation enacted.
6680L, 6800L, 7530L, 8400L, A-Belt - Copper Creek Mine	Ground instability led to a cave-in, endangering workers and equipment; immediate evacuation required.

External Distribution

Distribution

Reviewers

Name	Position	Date
No Data Available		