Pre-Op



Header

 Submission ID
 194426
 Submission Date
 2024-10-08 07:46:13

Form Created Date 2024-10-08 07:44:33 Date 2024-10-08

Submitted ByLachapelle, Rob-AdminSupervisorLachapelle, Rob-Admin

Site Creighton Mine Department/Job TG223037 7777-998-004

Area/Level 6680L Workplace Testing incident report attachments

Invertec Welder	IW021
Equipment Status	Up

Pre-Op

Shift	Days
Engine hours (Start of shift)	12
Comments or Defects	
Testing incident report attachments	

Equipment Inspection and Records

Items	Response	Additional information	Additional Response
Check condition of cables			
Check cable hook ups (in good condition, clear from excess wear, cuts etc.)			
Check adaptor knobs (in good condition, clear from excess wear, cuts etc.) - edit			
Check Main Connection (clear of debris)			
Wire line condition			

Pre-Op Photos

Front

2023-10-27 16:42:00



Left

2022-05-06 07:13:19



Back

2023-09-13 07:42:31



2022-10-27 14:50:03



Post-Op

Level End Shift	6680L
End Shift Workplace	Testing incident report attachments
Engine hours (End of Shift)	23
Other Comments	
Testing incident report attachments	

Post-Op photos

Front

2023-10-27 16:42:00



Left

2022-05-06 07:13:19



Back

2023-09-13 07:42:31



2022-10-27 14:50:03



Signature

Review

Context

Comment	By Who	Position	Created Date	Modified Date
---------	--------	----------	--------------	---------------

No Data Available

Distribution

Distribution

Reviewers

Name	Position	Date
------	----------	------

No Data Available