

Header


Title	"Deep Earth Explorers: Unearthing the Riches Below"		
Submission ID	193705	Submitted By	Lachapelle, Rob-Admin
Lineup Date	2024-07-08	Supervisor	Lachapelle, Rob-Admin
Site	Coleman Mine	Department/Job	CP220002
Shift	Afternoons	Crew	Production
Client Representative	Bryce Mining Corporation	Contact Info	555-123-4567, info@bryceminingcorp.com
Safety Topic	"Preventing rockfall accidents in mines"		
Communication Notes	Safety first: morning crew, today's focus is equipment maintenance. Stay alert and work together.		
Workplace Impacts	Safety hazards in mining can lead to injuries or fatalities.		

Shaft, Winch Building
Granite Quarry.

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
--------	----------------	-------------	------------	----------------

ID, Employee ID	No		-	-
-----------------	----	--	---	---

Images



Lineup Details

Details

Excavator, dump truck, bulldozer, drill rig.
--

Hazards

Location	Description
Shaft, Winch Building - Testing	Testing
Shaft, Winch Building - Testing PD-2042	Testing PD-2042
Shaft, Winch Building - Testing PD-2042	Testing PD-2042
Shaft, Winch Building - Testing PD-2042	Testing PD-2042
Shaft, Winch Building - Testing PD-2042	Testing PD-2042
Shaft, Winch Building - Testing PD-2042	Testing PD-2042
Shaft, Winch Building - Pit Control Center	Highwall collapse.
Shaft, Winch Building - Pit Control Center	Highwall collapse.
Shaft, Winch Building - Drill and Blast Department	High voltage electrical lines.
Shaft, Winch Building - Drill and Blast Department	High voltage electrical lines.
Shaft, Winch Building - Drill and Blast Department	High voltage electrical lines.
Shaft, Winch Building - Drill and Blast Department	High voltage electrical lines.

External Distribution

Distribution	rlachapelle@sofvie.com (Rob-Admin Lachapelle);lach.rob@icloud.com;dtsuciu@hotmail.com;lach.rob@gmail.com (Rob-User Lachapelle);dtsuciu@yahoo.com;
--------------	---

Reviewers

Name	Position	Date
No Data Available		