






Header

Title	Mining Safety Tips		
Submission ID	193847	Submitted By	Das, Pragati
Lineup Date	2024-07-17	Supervisor	Supervisor, Automation
Site	Creighton Mine	Department/Job	TG223037
Shift	Afternoons	Crew	Maintenance
Client Representative	Connor Stonehill	Contact Info	555-555-5555, cstonehill@email.com
Safety Topic	Emergency response planning.		
Communication Notes	<ul style="list-style-type: none"><li>- Wear proper safety gear</li><li>- Follow ventilation guidelines</li><li>- Always check equipment before use</li><li>- Stay alert and aware of surroundings</li></ul>		
Workplace Impacts	Prioritize safety to minimize accidents and injuries in mining workplace.		

7530L, 7680L, 8010L

Pit Control Center

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Images				
				
				

Lineup Details

Details
---------

- 
- Shift supervisor
  - Drillers
  - Blasters
  - Heavy equipment operators
  - Geologists
  - Safety officers
- 

External Distribution

Distribution	Bastien, Gibs; Ayotte, Joel
--------------	-----------------------------

---

Reviewers

Name	Position	Date
No Data Available		

---