

Header

Title	Equipment Safety Inspections		
Submission ID	193741	Submitted By	Lachapelle, Rob-Admin
Lineup Date	2024-07-17	Supervisor	Thom, Thom Thom
Site	Alamos Gold - Young and Davidson	Department/Job	TS222145
Shift	Days	Crew	Maintenance
Client Representative	Silver Ridge Mining Co.	Contact Info	Silver Ridge Mining Co., (555) 123-4567, info@silverridgemining.com
Safety Topic	Importance of Routine Equipment Safety Inspections for Mine Operation Safety		
Communication Notes	<ul style="list-style-type: none"><li>- Checked fluid levels; all within safe range.</li><li>- Inspected hydraulic systems; no leaks found.</li><li>- Gauges calibrated; reading accurate.</li><li>- Safety guards in place and secure.</li><li>- Brakes tested; functioning well.</li><li>- Lights and indicators operational.</li><li>- Tires checked; adequate tread depth.</li><li>- Emergency shutoff tested; fully operational.</li></ul>		
Workplace Impacts	Reduced downtime and incidents improve productivity and safety compliance.		

Field, Mobile Shop, Office, Surface, Yard

Westridge Coal Mine

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Rheume, Quade	No		245 - Excavator + Mini Ex	Primary Crusher, North Section, Lower Level
Images				



Lineup Details

Details

- Inspect PPE
- Conduct toolbox talk
- Check equipment
- Secure work zones
- Begin shift operations

External Distribution

Distribution

Reviewers

Name	Position	Date
No Data Available		