Lineup

Header

Title

	Inspection Highlights		
Submission ID	193750	Submitted By	Duggal, Manmeet Singh
Lineup Date	2024-07-17	Supervisor	Faulkner, Scott
Site	Monarques - Mine Beaufor	Department/Job	TG221003
Shift	Afternoons	Crew	construction
Client Representative	Atlantic Mineral Exploration Ltd.	Contact Info	555-123-4567, contact@atlanticmineralexploration.c

Safety Topic Regularly Check Brake Systems and Hydraulics to Prevent Mechanical Failures.

Communication Notes

Brakes functioning well.Hydraulics show no leaks.

- Tire treads in good condition.

- Lights operational.

Heavy Machinery

- Horn and signals working perfectly.

- No unusual engine noises.

- Fluid levels all correct.

- Safety guards in place.

- Controls responsive.

- Seatbelt secure.

Workplace Impacts Improved safety measures ensured; minor hydraulic leak identified and scheduled for repair.

Niv 132

Horizon Mining Operations Facility

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Duggal, Manmeet Singh	No	Winter Wear, Half Mask Respirator C/W P-100 Filers	R2629 - Knuckle Boom	Entrance to the main ventilation shaft in the North Quadrant.

Images







Lineup Details

Details

- Inspect PPE
- Check equipment
- Review hazards
- Assign tasks
- Conduct briefing

External Distribution

Distribution

Reviewers

Name	Position	Date
No Data Available		