Lineup

Header

Title

Inspection Highlights
Inspection Highlights

Heavy Machinery

Submission ID 193776 Submitted By Duggal, Manmeet Singh

Lineup Date 2024-07-22 Supervisor Faulkner, Scott

Site Monarques - Mine Beaufor Department/Job TG221003

Shift Afternoons Crew construction

Client Representative Atlantic Mineral Exploration Contact Info 555-123-4567,

Ltd. contact@atlanticmineralexploration.c

Safety Topic Regularly Check Brake Systems and Hydraulics to Prevent Mechanical Failures.

Communication Notes - Brakes functioning well.

- Hydraulics show no leaks.

- Tire treads in good condition.

- Lights operational.

- Horn and signals working perfectly.

- No unusual engine noises.

- Fluid levels all correct.

- Safety guards in place.

- Controls responsive.

- Seatbelt secure.

Workplace Impacts Improved safety measures ensured; minor hydraulic leak identified and scheduled for repair.

Surface

Horizon Mining Operations Facility

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Duggal, Manmeet Singh	No	Winter Wear, Half Mask Respirator C/W P-100 Filers	R2629 - Knuckle Boom	Entrance to the main ventilation shaft in the North Quadrant.

Images







Lineup Details

Details

- Inspect PPE
- Check equipment
- Review hazards
- Assign tasks
- Conduct briefing

External Distribution

Distribution

Reviewers

Name	Position	Date
No Data Available		