

Header




Title	Heavy Machinery Inspection Highlights		
Submission ID	193798	Submitted By	Duggal, Manmeet Singh
Lineup Date	2024-07-23	Supervisor	Faulkner, Scott
Site	Monarques - Mine Beaufor	Department/Job	TG221003
Shift	Afternoons	Crew	construction
Client Representative	Atlantic Mineral Exploration Ltd.	Contact Info	555-123-4567, contact@atlanticmineralexploration.c
Safety Topic	Regularly Check Brake Systems and Hydraulics to Prevent Mechanical Failures.		
Communication Notes	<ul style="list-style-type: none">- Brakes functioning well.- Hydraulics show no leaks.- Tire treads in good condition.- Lights operational.- Horn and signals working perfectly.- No unusual engine noises.- Fluid levels all correct.- Safety guards in place.- Controls responsive.- Seatbelt secure.		
Workplace Impacts	Improved safety measures ensured; minor hydraulic leak identified and scheduled for repair.		

Surface

Horizon Mining Operations Facility

Worker	Working Alone?	Special PPE	Eqpt. Type	Eqpt. Location
Suciu, Dan	No	Winter Wear, Half Mask Respirator C/W P-100 Filers	R2629 - Knuckle Boom	Entrance to the main ventilation shaft in the North Quadrant.

Images



Lineup Details

Details
<div><div>- Inspect PPE</div><div>- Check equipment</div><div>- Review hazards</div><div>- Assign tasks</div><div>- Conduct briefing</div></div>

External Distribution

Distribution

Reviewers

Name	Position	Date
No Data Available		